

Candura Instruments PV II™ Software installation instructions

- To install PV II™ on to your computer, insert USB key that is provided to you, then double click:

`USB_Drive_Letter:\Software\setup_PVII_x.x.x.exe`

Follow the instructions on screen to complete the installation processes.

Optional

If you have restricted access to install new software on your computer, you can still run PV II™ as a standalone program (without being installed on computer).

`USB_Drive_Letter:\Software\PVII (x.x.x Release)\PVII.exe`

Software – Extras

PV II setup file will determine whether the following dependencies from Microsoft are available on the local computer, then prompt the user to run the necessary dependency installation prior to installing Candura's software. If for some reasons this was not done automatically, the user can manually install these dependencies from each folders.

1. Microsoft .NET (dotNet) Framework v4.7.2 Offline Installer
 - PV II and MIV software requires minimum .NET Framework v4.5. Higher version is acceptable.
2. Visual C++ Redistributable for Visual Studio 2012
 - X64 for PV II
3. Visual C++ Redistributable for Visual Studio 2013
 - X64 for PV II
4. CustomExportFormat.PVIIcust - Use for PVII Custom Export. Please refer to PVII Users Guide – Data Export - Export to Custom